


Display Charts / Spreading Rate Charts

These charts employ time-tested diagonally striped patterns, having a strong visual impact that emphasizes variations in film opacity. They are therefore frequently used for hiding power display purposes, by means of drawdowns or brushouts. Gray stripes in Form 8H-GW provide reduced substrate contrast for use with low hiding power coatings. Spreading Rate Charts (Forms 8H and 8H-GW) are accurately 0.1 square meters (approximately one square foot) in area, and are used in brushout hiding tests at specified spreading rates as described in ASTM Method D 344.



Form 8A
5-1/2 x 10 in
140 x 254 mm
Design Area = 275 cm²



Form 8B
7-5/8 x 11-3/8 in
194 x 289 mm
Design Area = 425 cm²



Form 8K
8-5/8 x 11-1/4 in
219 x 285 mm
Design Area = 500 cm²

Spreading Rate Charts

Design Area = 1.076 ft² (1000 cm²)



Form 8H
11-1/4 x 17-1/4 in
286 x 438 mm



Form 8H-GW
11-1/4 x 17-1/4 in
286 x 438 mm

PACKAGING

Form No.	Box Quantity	Boxes per Case	Box Weight
8A	250	6	6 lb
8B	250	4	9 lb
8H	125	4	11 lb
8H-GW	125	4	11 lb
8K	250	4	11 lb